

9/17/2024 12:00:00

Owner Name: Kevin Hunter

Prepared As Of: AM

Model 3 Sedan 4D Standard Range Plus
Electric

Vehicle Description: 2020

TESLA

Year

Make

Model

5YJ3E1EA5LF606325

65,020

Black

| | No | Yes | | No | Yes | | No | Yes |
|------------------|--------------------------|-------------------------------------|------------------|-------------------------------------|-------------------------------------|-----------------------------|-------------------------------------|-------------------------------------|
| Cruise Control | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Leather Interior | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Radio | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| Theft Deterrent | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Manual | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Automatic | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| Power Windows | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Heated Seats | <input type="checkbox"/> | <input checked="" type="checkbox"/> | 4WD/AWD | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Power Seats | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Air Conditioning | <input type="checkbox"/> | <input checked="" type="checkbox"/> | 3 rd Row Seating | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Power Door Locks | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Power Sunroof | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Rear Entertainment | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Other Items:

| | Good | Fair | Poor | | Good | Fair | Poor |
|---------------------|--------------------------|-------------------------------------|--------------------------|--------------------|--------------------------|-------------------------------------|--------------------------|
| Grill | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Left Fender | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Front Bumper | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Left Door | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Hood | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Left Quarter Panel | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Right Fender | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Interior | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Right Door | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Engine | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Right Quarter Panel | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Brakes | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Lights | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Paint Finish | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Rear Bumper | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Tires | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Roof | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | | |

Comments

Valuation Report: Based on Edmunds Evaluation

| | Value |
|-------------------------|--------------------|
| Average Base Value: | \$19,485.00 |
| Mileage Class: Average: | |
| Add-ons/Deducts: | - |
| | - |
| | - |
| | - |
| | - |
| Appraised Value: | \$19,485.00 |

The above vehicle condition report was prepared for the purpose of making a secured loan on said collateral. By signing below, preparer of report certifies that information regarding collateral was ascertained via visual inspection or provided and collected in good faith from owner or owner's representative. Information as to vehicle's condition has been applied with due diligence in conjunction with current publications by an experienced valuation specialist. No other representations, direct or indirect, material or immaterial, are made, assured or implied by this report of any other member of 722 staff or management.

/s/ Sharon Monroe

Collateral Valuation Services, LLC
P O Box 8361, Cincinnati, Ohio 45208
(513) 284-8539

Serial Number (VIN)

Mileage

Plate

Color

EXHIBIT 1